

Change of shaftseal on BUUS Iceflakers.

From type 129572



to 011299



Before and after the repair


Old type shaft seal




After the repair




The drum is dismounted



The outer parts of the shafts are removed




A thread for the adapter
is made



The adapter



The adapter is mounted



The adapter is mounted
and the drum ready to
be reinstalled



Ready for shipment



Time: 5 to 8 hours